REMOVING CORING ROD AFTER CASTING

KNDX, KNSU: REMOVE WHILE STILL WARM (NOT HOT), TYPICALLY $\frac{1}{2}$ hr.

KNSB: REMOVE AFTER GRAIN HARDENS (24-48 hrs.)

